

Overview Electrical Machines and Drives




- 7-9 1: Introduction, Maxwell's equations, magnetic circuits
- 11-9 1.2-3: Magnetic circuits, Principles
- 14-9 3-4.2: Principles, DC machines
- 18-9 4.3-4.7: DC machines and drives
- 21-9 5.2-5.6: IM introduction, IM principles
- 25-9 Guest lecture Emile Brink
- 28-9 5.8-5.10: IM equivalent circuits and characteristics
- 2-10 5.13-6.3: IM drives, SM
- 5-10 6.4-6.13: SM, PMACM
- 12-10 6.14-8.3: PMACM, other machines
- 19-10: rest, questions
- 9-11: exam

Permanent magnet AC machines

(6.13)

- Introduction
- Calculation example
- Brushless DC motor (rectangular / trapezoidal waveforms)
- PMSM (sinusoidal waveforms)
- For these machine types
 - Construction
 - Electromotive force
 - Voltage equations and equivalent circuit
 - Power balance
 - Force or torque

PM AC machine



Rotor layouts

1 surface mounted magnets

- $L_d \approx L_q$
- L small because of large air gap

2 inset magnets


- $L_d < L_q$
- reluctance torque

3 embedded magnets, radial magnetization

- $L_d < L_q$
- reluctance torque

4 embedded magnets, circumferential magnetization

- flux concentration



Permanent magnet AC machines

(6.13)


- Introduction
- Calculation example
- Brushless DC motor (rectangular / trapezoidal waveforms)
- PMSM (sinusoidal waveforms)
- For these machine types
 - Construction
 - Electromotive force
 - Voltage equations and equivalent circuit
 - Power balance
 - Force or torque

PM AC machine: calculation example



- air gap radius r_s
- axial length l_s
- magnet length l_m
- air gap length l_g
- number of turns N_s
- remanent flux density B_{rm}
- recoil permeability μ_{rm}
- rotor speed ω_m

Determine and sketch

- air gap flux density in gap
- flux linkage as a function of rotor position
- induced voltage



PM AC machine



PM AC machine

Using Ampère's law:

$$\oint_{C_m} \vec{H} \cdot \vec{\tau} \, ds = \iint_{S_m} \vec{J} \cdot \vec{n} \, dA \quad 2H_m l_m + 2H_g l_g = 0$$

Magnetic flux continuity

$$\oiint_S \vec{B} \cdot \vec{n} \, dA = 0 \quad B_m = B_g$$

BH curve of magnet

$$B_m = \mu_0 \mu_{rm} H_m + B_r$$

BH curve of air

$$B_g = \mu_0 H_g$$

Result

$$B_g = \frac{l_m}{l_m + \mu_{rm} l_g} B_r$$

PM AC machine

For one phase without load:

$$\lambda_{\max} = NBA = N_s B_g \pi r_s l_s$$

$$E_{pm\max} = \frac{d\lambda}{dt} = 4f\lambda_{pm\max} = 2N_s B_g r_s l_s \omega_m$$

$$E_{pm\max} = Blv$$

Permanent magnet AC machines

(6.13)

- Introduction
- Calculation example
- Brushless DC motor (rectangular / trapezoidal waveforms)
- PMSM (sinusoidal waveforms)
- For these machine types
 - Construction
 - Electromotive force
 - Voltage equations and equivalent circuit
 - Power balance
 - Force or torque


Construction: PMAC or BDCM

PMSM:

- sinusoidal B
- distributed windings
- sinusoidal voltage
- sinusoidal currents
- continuous position sensor^{P_a}
- smooth force

BDCM:

- rectangular B
- concentrated windings
- trapezoidal voltage
- rectangular currents
- 6 step position sensor
- force ripple




Brushless DC machine


Name may be confusing

Idea:

- PM excitation on rotor: no brushes
- mechanic commutator replaced by converter






(a)




Brushless DC machine

Why trapezoidal voltage?



Brushless DC machine operation

- Six step operation
- Six times per revolution position information necessary



PM AC machine

For one phase without load:

$$\lambda_{\max} = NBA = N_s B_g \pi r_s l_s$$

$$E_{pm\max} = \frac{d\lambda}{dt} = 4f\lambda_{pm\max} = 2N_s B_g r_s l_s \omega_m$$

$$E_{pm\max} = Blv$$

BDCM voltage equations

Maxwell, Faraday: $u = Ri + \frac{d\lambda}{dt}$

$$\begin{cases} \lambda_{sa} = L_{sa}i_{sa} + M_{sab}i_{sb} + M_{sab}i_{sc} + \lambda_{pma}(\theta) \\ \lambda_{sb} = M_{sab}i_{sa} + L_{sa}i_{sb} + M_{sab}i_{sc} + \lambda_{pmb}(\theta) \\ \lambda_{sc} = M_{sab}i_{sa} + M_{sab}i_{sb} + L_{sa}i_{sc} + \lambda_{pmc}(\theta) \end{cases}$$


No star-point connection: $i_{sa} + i_{sb} + i_{sc} = 0$

$$L_s = L_{sa} - M_{sab}$$

$$\begin{cases} \lambda_{sa} = (L_{sa} - M_{sab})i_{sa} + \lambda_{pma}(\theta) = L_s i_{sa} + \lambda_{pma}(\theta) \\ \lambda_{sb} = (L_{sa} - M_{sab})i_{sb} + \lambda_{pmb}(\theta) = L_s i_{sb} + \lambda_{pmb}(\theta) \\ \lambda_{sc} = (L_{sa} - M_{sab})i_{sc} + \lambda_{pmc}(\theta) = L_s i_{sc} + \lambda_{pmc}(\theta) \end{cases}$$


BDCM voltage equations

$$u_a = Ri_a + \frac{d\lambda_a}{dt}$$



Single-phase equivalent circuit

$$\begin{cases} u_a = Ri_a + L_s \frac{di_a}{dt} + e_{pma} \\ u_b = Ri_b + L_s \frac{di_b}{dt} + e_{pmb} \\ u_c = Ri_c + L_s \frac{di_c}{dt} + e_{pmc} \end{cases}$$



Three-phase equivalent circuit

BDCM torque

Always two phases conducting:

$$P = u_x i_x + u_y i_y = 2RI^2 + 2 \frac{d \frac{1}{2} L_s I^2}{dt} + 2E_{pm \max} I$$

Electrical input power = Losses + Increase stored energy + Mechanical output power

Torque:

$$T = \frac{P}{\omega_m} = \frac{2IE_{pm \max}}{\omega_m} = 4B_g N_s l_s r_s I$$

$$T = r_s F = r_s B l I$$

Power balance gives same result as Lorentz

BDCM pros and cons

- Main problem:
 - Six times per period irregularities in the torque because
 - Hall sensors different and positioned with limited accuracy
 - Motor coils are slightly different
 - The EMF (voltage induced by magnets) are different
 - Controller branches are different
 - Current can not be a square wave. Why not?
 - Consequences
 - Not nice for position servo
 - Can be improved by hysteresis in Hall sensors
- Strengths BDCM
 - Simple controller with six step position sensor
 - Sensorless operation possible at higher speeds.

Permanent magnet AC machines

(6.13)

- Introduction
- Calculation example
- Brushless DC motor (rectangular / trapezoidal waveforms)
- PMSM (sinusoidal waveforms)
- For these machine types
 - Construction
 - Electromotive force
 - Voltage equations and equivalent circuit
 - Power balance
 - Force or torque


Construction: PMAC or BDCM

PMSM:




- sinusoidal B
- distributed windings
- sinusoidal voltage
- sinusoidal currents
- continuous position sensor
- smooth force

BDCM:



- rectangular B
- concentrated windings
- trapezoidal voltage
- rectangular currents
- 6 step position sensor
- force ripple



PM AC machine



PM synchronous machine




PM synchronous machine

$$\left\{ \begin{array}{l} \Phi_{pma} = -\hat{\Phi}_{pm} \cos\left(\frac{\pi}{\tau_p} x\right) \\ \Phi_{pmb} = -\hat{\Phi}_{pm} \cos\left(\frac{\pi}{\tau_p} x - \frac{2}{3}\pi\right) \\ \Phi_{pmc} = -\hat{\Phi}_{pm} \cos\left(\frac{\pi}{\tau_p} x - \frac{4}{3}\pi\right) \end{array} \right.$$

Cosinusoidal because of

- skewing
- end teeth

How can the voltage be calculated?



PMSM voltage equations

$$u_a = Ri_a + \frac{d\lambda_a}{dt}$$


$$\lambda_a = L_{sa}i_a + M_{sab}i_b + M_{sab}i_c + N\Phi_{pma}$$

$$L_s = L_{sa} - M_{sab}$$


$$u_a = Ri_a + L_s \frac{di_a}{dt} + e_{pma}$$

$$u_b = Ri_b + L_s \frac{di_b}{dt} + e_{pmb}$$

$$u_c = Ri_c + L_s \frac{di_c}{dt} + e_{pmc}$$



Single-phase equivalent circuit



Three-phase equivalent circuit

PMSM voltage equations

$$\begin{aligned}\lambda_a &= L_{sa}i_a + M_{sab}i_b + M_{sac}i_c + N\Phi_{pma} \\ &= L_s i_a + N\Phi_{pma}\end{aligned}$$

$$\Phi_{pma} = -\hat{\Phi}_{pm} \cos\left(\frac{\pi}{\tau_p} x\right)$$



$$\begin{cases} u_a = Ri_a + L_s \frac{di_a}{dt} + e_{pma} \\ u_b = Ri_b + L_s \frac{di_b}{dt} + e_{pmb} \\ u_c = Ri_c + L_s \frac{di_c}{dt} + e_{pmc} \end{cases}$$

$$\begin{cases} e_{pma} = \hat{e}_{pm} \sin\left(\frac{\pi}{\tau_p} x\right) \\ e_{pmb} = \hat{e}_{pm} \sin\left(\frac{\pi}{\tau_p} x - \frac{2}{3}\pi\right) \\ e_{pmc} = \hat{e}_{pm} \sin\left(\frac{\pi}{\tau_p} x - \frac{4}{3}\pi\right) \end{cases}$$

What should be the current phase to make maximum force?

PMSM currents

$$\begin{cases} i_a = \hat{i} \sin\left(\frac{\pi}{\tau_p} x\right) \\ i_b = \hat{i} \sin\left(\frac{\pi}{\tau_p} x - \frac{2}{3} \pi\right) \\ i_c = \hat{i} \sin\left(\frac{\pi}{\tau_p} x - \frac{4}{3} \pi\right) \end{cases}$$



PMSM power and force

$$p = u_a i_a + u_b i_b + u_c i_c$$


$$p = R i_a^2 + R i_b^2 + R i_c^2 + \frac{d \frac{1}{2} L (i_a^2 + i_b^2 + i_c^2)}{dt} + e_{pma} i_a + e_{pmb} i_b + e_{pmc} i_c$$

$$p = \frac{3}{2} R \hat{i}^2 + \frac{dW_f}{dt} + \frac{3}{2} \hat{e}_{pm} \hat{i} = p_{Cu} + p_f + p_{mech}$$


Maximum three-phase force:
$$F = \frac{p_{mech}}{v} = \frac{3 \hat{e}_{pm} \hat{i}}{2v} = \frac{3}{2} \frac{\pi}{\tau_p} N \hat{\Phi}_{pm} \hat{i}$$

Voltage
$$\hat{u} = \sqrt{(R \hat{i} + \omega N \hat{\Phi}_{pm})^2 + (\omega L \hat{i})^2} \quad \omega = \frac{\pi}{\tau_p} \frac{dx}{dt}$$

Example: Archimedes Wave Swing




Linear AWS generator



Linear generator AWS



Measurement



Permanent magnet AC machines

(6.13)

- Introduction
- Calculation example
- Brushless DC motor (rectangular / trapezoidal waveforms)
- PMSM (sinusoidal waveforms)
- For these machine types
 - Construction
 - Electromotive force
 - Voltage equations and equivalent circuit
 - Power balance
 - Force or torque

Overview Electrical Machines and Drives

- 7-9 1: Introduction, Maxwell's equations, magnetic circuits
- 11-9 1.2-3: Magnetic circuits, Principles
- 14-9 3-4.2: Principles, DC machines
- 18-9 4.3-4.7: DC machines and drives
- 21-9 5.2-5.6: IM introduction, IM principles
- 25-9 Guest lecture Emile Brink
- 28-9 5.8-5.10: IM equivalent circuits and characteristics
- 2-10 5.13-6.3: IM drives, SM
- 5-10 6.4-6.13: SM, PMACM
- 12-10 6.14-8.3: PMACM, other machines
- 19-10: rest, questions
- 9-11: exam