

Overview Electrical Machines and Drives

- 7-9 1: Introduction, Maxwell's equations, magnetic circuits
- 11-9 1.2-3: Magnetic circuits, Principles
- 14-9 3-4.2: Principles, DC machines
- 18-9 4.3-4.7: DC machines and drives
- 21-9 5.2-5.6: IM introduction, IM principles
- 25-9 Guest lecture Emile Brink
- 28-9 5.8-5.10: IM equivalent circuits and characteristics
- 2-10 5.13-6.3: IM drives, SM
- 5-10 6.4-6.13: SM, PMACM
- 12-10 6.14-8.3: PMACM, other machines
- 19-10: rest, questions
- 9-11: exam


DC Machines

- Introduction, construction (4.2)
- Principle of operation and basic calculations (4.2)
 - air gap flux density (1.1)
 - armature turn voltage and commutation (4.2.2)
 - armature windings (4.2.3)
 - total armature voltage (4.2.4)
 - torque (4.2.5)
 - magnetisation curve (4.2.6)
- Armature reaction, interpoles, compensating winding (4.3)
- Characteristics, means to control speed (4.4)
- DC machine drives (4.5)
- PMDC machines / PCB machines (4.6, 4.7)

Assumptions for calculations


- steady state (mechanical and electrical)
- the air gap is so small that the flux density does not change in radial direction
- the air gap is so small that the flux density crosses the air gap perpendicular
- iron losses are negligible
- the magnetic permeability of iron is infinite

Air gap flux density



- The field winding around one pole has N_f turns and carries a current I_f
- Calculate the air gap flux density between the poles and the rotor


Flux density




$$\oint_{C_m} \vec{H} \cdot \vec{\tau} ds = \iint_{S_m} \vec{J} \cdot \vec{n} dA$$

$$2H_g l_g = 2N_f I_f$$


$$B_g = \frac{\mu_0 N_f I_f}{l_g}$$



Flux density



- Sketch flux linkage of a turn on the rotor
- Calculate the maximum voltage induced in turn from Faraday's law



Armature turn voltage


At $\theta=0$, the flux linkage is minimum

$$e_t = \frac{d\lambda}{dt} = \frac{d}{dt} \iint_{S_e} \vec{B} \cdot \vec{n} dA$$


$$= -l \frac{d}{dt} \int_{\theta}^{\theta+\pi} B(\theta) r d\theta$$

$$= lrB(\theta) \frac{d\theta}{dt} - lrB(\theta + \pi) \frac{d\theta}{dt}$$


$$= 2lrB(\theta)\omega = 2lB(\theta)v$$





(a)




Commutator as rectifier




C_a, C_b -commutator segment




Commutation



Commutating coil in
interpolar region: no
induced voltage



Armature windings



- English: turn, coil, winding
- Dutch: winding, spoel, wikkeling

Mechanical and electrical angles




FIGURE 4.16 Mechanical and electrical degrees. (a) Four-pole dc machine. (b) Flux density distribution.

$$\theta_e = \frac{p}{2} \theta_m$$

$$\omega_e = \frac{p}{2} \omega_m$$

DC Machines

- Introduction, construction (4.2)
- Principle of operation and basic calculations (4.2)
 - air gap flux density (1.1)
 - armature turn voltage and commutation (4.2.2)
 - armature windings (4.2.3)
 - total armature voltage (4.2.4)
 - torque (4.2.5)
 - magnetisation curve (4.2.6)
- Armature reaction, interpoles, compensating winding (4.3)
- Characteristics, means to control speed (4.4)
- DC machine drives (4.5)
- PMDC machines / PCB machines (4.6, 4.7)

Armature voltage

An armature winding has N turns
with a parallel paths
and therefore N/a series-connected turns

For the turn voltage, we found $e_t = 2lr\omega_m B(\theta)$

The average is lower: $\bar{e}_t = 2lr\omega_m \bar{B}(\theta)$

Flux per pole $\Phi = \iint \vec{B} \cdot \vec{n} \, dA = l \int_0^{2\pi/p} B(\theta) r \, d\theta = \frac{2\pi}{p} rl \bar{B}(\theta)$

Using this, the turn voltage is given by $\bar{e}_t = \frac{p}{\pi} \Phi \omega_m$

Therefore $E_a = \frac{N}{a} \bar{e}_t = \frac{Np}{\pi a} \Phi \omega_m = K_a \Phi \omega_m$

Voltage and torque from power balance

$$U = RI_a + L \frac{dI_a}{dt} + K_a \Phi \omega_m$$


$$P = UI_a = RI_a^2 + I_a L \frac{dI_a}{dt} + I_a K_a \Phi \omega_m$$

Power balance:

$$P = P_{Cu} + P_f + P_{mech}$$

Therefore

$$T = \frac{P_{mech}}{\omega_m} = K_a \Phi I_a$$



Electromagnetic torque from Lorenz



$$F_c = B(\theta)lI_c = B(\theta)l\frac{I_a}{a}$$

$$T_c = rF_c = B(\theta)rl\frac{I_a}{a}$$

$$\bar{T}_c = \bar{B}(\theta)rl\frac{I_a}{a} = \frac{p}{2\pi a}\Phi I_a$$

$$T = 2N\bar{T}_c = \frac{Np}{\pi a}\Phi I_a = K_a\Phi I_a$$


$$P = \omega_m T = \omega_m K_a \Phi I_a = E_a I_a$$




Lorenz force gives the same result as power balance.

Magnetic circuit

Which part saturates first?
Why?



(a)



Magnetization curve




FIGURE 4.24 Test result: magnetization curve.

Why is this not a straight line?
Why does it not start from zero?


DC Machines

- Introduction, construction (4.2)
- Principle of operation and basic calculations (4.2)
- Armature reaction, interpoles, compensating winding (4.3)
- Characteristics, means to control speed (4.4)
- DC machine drives (4.5)
- PMDC machines / PCB machines (4.6, 4.7)


Armature reaction

- Section 4.3 (Sen) has the title “DC generators”
- DC machines are hardly used as generators
- The operating principles are the same in motoring and generating
- Therefore, we only look at constructional aspects of DC machines discussed in 4.3, which are present in DC motors as well as in DC generators:
 - compensating winding (Dutch: compensatiewikkeling)
 - interpoles (Dutch: hulppolen)
- Both are related to armature reaction


Armature reaction



(a)






(b)




Consequences armature reaction


- Saturation
- Commutation problems



Compensation winding



(a)




(b)


- Saturation problem reduced
- Expensive; only applied in machines that are often heavily loaded.
Why in these machines?

Interpoles


Armature reaction produces a flux density in the interpolar region, so that a voltage is induced in the commutating coil. This voltage opposes commutation. Interpoles reverse the direction of this flux density to induce a voltage that accelerates commutation.




(a)




(b)




(c)



(d)



(e)




(f) Φ_a , Φ_i oppose each other, irrespective of direction of I_a .


DC Machines

- Introduction, construction (4.2)
- Principle of operation and basic calculations (4.2)
- Armature reaction, interpoles, compensating winding (4.3)
- Characteristics, means to control speed (4.4)
 - Connections of DC machines
 - Separately excited DC machine
 - Series connected DC machine
- DC machine drives (4.5)
- PMDC machines / PCB machines (4.6, 4.7)


Connections of DC machines




(a)




(b)



(c)



Short shunt



Long shunt

Separately excited DC machines

Pole flux does not depend on armature voltage and load

$$T = K_a \Phi I_a$$


$$E_a = \omega_m K_a \Phi$$

$$U_t = R_a I_a + E_a$$

$$\omega_m = \frac{U}{K_a \Phi} - \frac{R_a I_a}{K_a \Phi} = \frac{U}{K_a \Phi} - \frac{R_a T}{(K_a \Phi)^2}$$

How to control speed?

Calculate no-load speed and stall torque.



Torque speed characteristic










FIGURE 4.51 Torque–speed characteristics of a separately excited dc motor.

- Where are motor, generator and plugging operation?
- Speed control by means of
 - Voltage control: what happens if the voltage is increased?
 - Field control: what happens if the current is increased?
 - Resistance control: old-fashioned



Voltage control





Field control



Are the characteristics of (c) parallel?



Series DC machine (universal motor)



$$\Phi = K_1 I_a$$

$$T = K_a \Phi I_a = K_a K_1 I_a^2$$

Neglecting saturation!

What happens to the speed when the torque is zero?

Series DC motor

$$\Phi = K_1 I_a$$

$$T = K_a \Phi I_a = K_a K_1 I_a^2$$

$$U_t = R_a I_a + E_a = R_a I_a + K_a \Phi \omega_m = R_a I_a + K_a K_1 I_a \omega_m$$

$$I_a = \frac{U_t}{R_a + K_a K_1 \omega_m}$$

$$T = K_a \Phi I_a = K_a K_1 I_a^2 = K_a K_1 \frac{U_t^2}{(R_a + K_a K_1 \omega_m)^2}$$

$$\omega_m = \pm \frac{U_t}{\sqrt{K_a K_1 T}} - \frac{R_a}{K_a K_1}$$

DC machines

- Introduction, construction (4.2)
- Principle of operation and basic calculations (4.2)
- Armature reaction, interpoles, compensating winding (4.3)
- Characteristics, means to control speed (4.4)
- DC machine drives (4.5)
 - Ward-Leonard system
 - Power electronics (Rectifier, Chopper)
 - Closed loop control
- PMDC machines / PCB machines (4.6, 4.7)

Overview Electrical Machines and Drives

- 7-9 1: Introduction, Maxwell's equations, magnetic circuits
- 11-9 1.2-3: Magnetic circuits, Principles
- 14-9 3-4.2: Principles, DC machines
- 18-9 4.3-4.7: DC machines and drives
- 21-9 5.2-5.6: IM introduction, IM principles
- 25-9 Guest lecture Emile Brink
- 28-9 5.8-5.10: IM equivalent circuits and characteristics
- 2-10 5.13-6.3: IM drives, SM
- 5-10 6.4-6.13: SM, PMACM
- 12-10 6.14-8.3: PMACM, other machines
- 19-10: rest, questions
- 9-11: exam